


OPERATION INSTRUCTIONS

CAUTION

The PSX-2 is designed to exchange power steering fluid and approved power steering flush chemicals. Using the PSX-2 for brake fluid and other liquids may damage the pump seals and void the warranty.

EXCHANGE

1. Verify that there is enough fluid in the New Fluid Tank and sufficient space in the Used Fluid Tank for the exchange procedure. The vehicle engine must be off.
 2. Remove the Power Steering Fluid Reservoir Cover and submerge Service Hose into the reservoir.
 3. Remove the used fluid from the Reservoir by pressing the rear of the switch on the control wand.
 4. Refill the Reservoir by pressing the front of the switch on the control wand.
- Suggestion:** Fill new fluid level slightly above steering rack return line.
5. Start the vehicle and turn the steering wheel all the way clockwise and then all the way counter-clockwise (lock to lock).
 6. Turn the vehicle engine off.
 7. Repeat steps 3 through 6 until the desired level of fluid exchange is achieved.



Caution: Do not allow Used Tank to overflow

| REPLACEMENT PARTS | |
|------------------------|---------------------|
| Pump | 320-80016-00 |
| New Fluid Tank | 315-80004-00 |
| Used Fluid Tank | 315-80005-00 |
| Hose Cap | 028-80250-18 |
| Switch | 024-80088-00 |
| Filter, Bowl | 026-80247-00 |
| Filter, Mesh | 026-80248-00 |

EC Declaration of Conformity for Machinery Directive 98/37/EC



MAHLE Aftermarket Inc.
10 Innovation Drive
York, Pennsylvania 17402 USA
Phone: 717-840-0678

Herewith declares that:

- PSX-2 Power Steering Fluid Exchanger
- is in conformity with the provisions of the Machinery Directive (directive 98/37/EC) and with the national implementing legislation
- is in conformity with the provisions of the following other EC directives:

Electromagnetic Compatibility (EMC) Directive 89/336/EEC
Electromagnetic Emissions EN 61000-6-4: 2001
Electromagnetic Immunity EN 61000-6-2: 1999

The DFX-1 is certified to the EMC Directive like the ATX-2 tested by:

TÜV America Inc.
1775 Old Highway 8 NW Ste. #104
New Brighton, MN 55112
Phone: 651-638-0262



Eric I. Shultz

Vice President - Technology
Dated: February 20, 2013

MAHLE Aftermarket Inc.

10 Innovation Drive
York, PA 17402 - USA
1-800-468-2321 x1
www.servicesolutions.mahle.com