



MAHLE Clevite Inc., RTI Division
10 Innovation Drive
York, PA 17402 USA
Phone: 717-840-0678
Web-site: www.rtitech.com

Bulletin No: 562-80008-00 Rev A

Issued: December 14, 2007

Subject:	NitroPRO Valve Stem Caps
-----------------	--------------------------

Model Numbers Affected:	All NitroPRO Nitrogen Filling Equipment
Manufacture Dates:	All
Serial Numbers Affected:	All
Tools Required:	None
Parts Required:	None
Supplemental Document:	None
Action Required:	Proper use of aluminum or brass valve stem caps

Please be aware, certain automobile OEM's have issued service bulletins advising against the use of valve stem caps manufactured from either aluminum or brass due to cap removal difficulties caused by corrosion in certain geographic areas of the country.

Because of the wide variety of OEM vehicle makes and models **AND** the large quantity of aftermarket wheel, tire and wheel/tire accessory manufacturers in today's marketplace, RTI considers it to be the responsibility of the installing service facility in **ALL** instances to determine the application suitability of RTI valve stem caps.

RTI assumes no responsibility for the misapplication of its valve stem caps regardless of make or model of vehicle or installed aftermarket equipment and/or accessories.