

AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple listee model(s) identified on the correlation page of the Listing Report.

Applicant: RTI Technologies, Inc.
P.O. Box 3099
4075 East Market Street
York, PA 17402-0099

Contact: Name: Mr. Thomas Crandall Phone: (717)840-0678 FAX: (717)755-8304

Manufacturer: Same As Applicant

Party Authorized To Apply Mark: Same as Manufacturer

Report Issuing Office: Intertek, Cortland, NY 13045

Report No.: 525122

Product Covered: Model Numbers TC700, TC700-R134a, TC2700, TC2770, RRC770, RRC770-R134a, RRC771, AC790, AC790-R134a, AC771, AC800, RHS780, RHS730

Description: The product covered by this report is a Refrigerant Recovery/Recycling unit. The unit removes contaminated refrigerant from a mobile air conditioner. Then it purifies it to less than the specified levels in SAE-J1991 or SAE-J2210. The unit has an internal storage cylinder that may hold up to approximately 10 pounds of clean refrigerant. The TC700 and the RRC770 purifies R-12 only. The RRC771, TC700-R134a and the RRC770-R134a process R-134a only and the AC800 and TC2700 process either R-12 or R-134a.

The unit is provided with a No. 16 AWG, 3 conductor power supply cord for connection to the supply source. The AC and TC2700 may be operated with a DOT storage tank. If the DOT tank is used then the overfill protective device must be part of the tank and the field installed connection cord must be installed in through the provided knock out.

Standard(s): Standard for Safety Refrigerant Recovery/Recycling Equipment (UL 1963, Second Edition) Refrigeration Equipment (CAN/CSA-C22.2 No. 120-M91)

This document is the property of Intertek Testing Services and is not transferable. Only the Applicant may reproduce this document. The certification mark(s) may be applied only at the above noted location of the Party Authorized To Apply Mark.



Authorized by: William T. Starr Date: October 15, 2004
William T. Starr, Certification Manager

Control Number: 71153

This document supercedes all previous Authorizations to Mark for the noted Report Number.