

MAHLE Clevite Inc., RTI Division 10 Innovation Drive York, PA 17402 USA Phone: 717-840-0678

Web-site: www.rtitech.com

**Bulletin No:** 562-80009-00

January 9, 2008

**Subject:** A/C Equipment Registration with EPA

Issued:

Model Numbers Affected:	All A/C Recovery-Recycling Equipment	
Manufacture Dates:	Commencing January 1, 2008	
Serial Numbers Affected:	All	
Tools Required:	None	
Parts Required:	None	
Supplemental Document:	035-80064-00 (Rev A)	
Action Required:	Equipment owner must submit the form to a regional EPA Office to register each piece of A/C recovery and recycling equipment.	

EPA has rewritten Section 609 of the Clean Air Act – Part of the new J2788 implementation.

Owners of A/C recovery and recycling equipment must submit a form to the EPA to register each piece of equipment.

Previously the forms were mailed to EPA Headquarters in Washington, DC.

Commencing January 1, 2008, these forms must be mailed to an EPA Regional Office.

RTI includes this form with every A/C machine. This revised form (see next two pages) lists the mailing addresses for the EPA regional offices.

The form will also be posted on the RTI web-site for downloading.



The New RHS980

## MVAC RECOVER, RECOVER/RECYCLE OR RECOVER/RECYCLE/RECHARGE EQUIPMENT CERTIFICATION FORM

NAME OF ESTABLISHMENT  STREET  CITY, STATE, ZIP CODE	<ul> <li>SEND THIS FORM TO THE EPA</li> <li>REGIONAL OFFICE LISTED UNDER</li> <li>YOUR STATE OR TERRITORY IN</li> <li>WHICH THE ESTABLISHMENT IS</li> <li>LOCATED.</li> </ul>
TELEPHONE NUMBER  2 NAME OF EQUIPMENT MANUFACTURER & MODEL NU	MAILING ADDRESSES CAN BE FOUND ON THE REVERSE SIDE OF THIS FORM.
SERIAL NUMBER(S)  YEAR  I certify that I have approved recover recover/recycle, or recover/recycle/recharacteristics equipment under Section 609 of the Clean Act. I certify that only properly trained a certified technicians operate the equipment that the information given above is true a correct.	rge Air and and
SIGNATURE OF OWNER/OPERATOR DATE	
NAME (PRINT) TITLE	

## MVAC RECOVER, RECOVER/RECYCLE OR RECOVER/RECYCLE/RECHARGE EQUIPMENT CERTIFICATION FORM INSTRUCTIONS

Motor vehicle refrigerant recover, recover/recycle, or recover/recycle/recharge equipment must be acquired by January 1, 1992 and certified to EPA on or before January 1, 1993 under Section 609 of the Clean Air Act. To certify your equipment, please complete the above form according to the following instructions and mail to the appropriate EPA region based on where your establishment is located.

- 1 Please provide the name, address, and telephone number of the establishment where the equipment is located.
- 2 Please provide the name brand, model number, year and serial number(s) of the equipment acquired for use at the above establishment.
- 3 The certification statement must be signed by the person who has acquired the equipment (the person may be the owner of the establishment or another responsible officer). The person who signs is certifying that they have acquired the equipment, that each individual authorized to use the equipment is properly trained and certified, and that the information provided is true and correct.

035-80064-00 (Rev A)

## **EPA REGIONAL OFFICES**

Send your form to the EPA office listed under the state or territory in which the establishment is located.

- Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont CAA section 609 Enforcement Contact; EPA Region I; Mail Code SEA; JFK Federal Building; One Congress Street, Suite 1100; Boston, MA 02114-2023
- New York, New Jersey, Puerto Rico, Virgin Islands
  CAA section 609 Enforcement Contact; EPA Region II (2DECA-AC); 290
  Broadway, 21st Floor; New York, NY 10007-1866
- Delaware, District of Columbia, Maryland, Pennsylvania, Virginia, West Virginia CAA section 609 Enforcement Contact; EPA Region III--Wheeling Operations Office; Mail Code 3AP12; 303 Methodist Building; 11th and Chapline Streets; Wheeling, WV 26003
- Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee

CAA section 609 Enforcement Contact; EPA Region IV(APT-AE); Atlanta Federal Center; 61 Forsyth Street, SW.; Atlanta, GA 30303

- Illinois, Indiana, Michigan, Minnesota, Ohio, Wisconsin
  CAA section 609 Enforcement Contact, EPA Region V (AE17J); 77 West
  Jackson Blvd.; Chicago, IL 60604-3507
- Arkansas, Louisiana, New Mexico, Oklahoma, Texas CAA section 609 Enforcement Contact; EPA Region VI (6EN-AA); 1445 Ross Avenue, Suite 1200; Dallas, Texas 75202
- lowa, Kansas, Missouri, Nebraska
  CAA section 609 Enforcement Contact; EPA Region VII; Mail Code APCO/
  ARTD; 901 North 5th Street; Kansas City, KS; 66101
- Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming
  CAA section 609 Enforcement Contact, EPA Region VIII, Mail Code 8ENF-T,
  999 18th Street, Suite 500, Denver, CO 80202-2466
- American Samoa, Arizona, California, Guam, Hawaii, Nevada
  CAA section 609 Enforcement Contact; EPA Region IX; Mail Code AIR-5; 75
  Hawthorne Street; San Francisco, CA 94105
- Alaska, Idaho, Oregon, Washington
  CAA section 609 Enforcement Contact; EPA Region X (OAQ-107); 1200 Sixth
  Avenue; Seattle, WA 98101